



Free Questions for H35-460 by certsdeals

Shared by Roberson on 29-01-2024

For More Free Questions and Preparation Resources

Check the Links on Last Page

Question 1

Question Type: MultipleChoice

When verifying the uplink 5G Only offload effect of the NSA network, under normal circumstances, only the NR side has uplink traffic, and the rate is stable, while the LTE side tracks no rate

Options:

A- Correct

B- Errors

Answer:

B

Question 2

Question Type: MultipleChoice

When commissioning NR devices, only the "Electronic Serial Number" and "Software Version" can be directly modified in the "Plug and Play" window

Options:

A- Correct

B- Errors

Answer:

A

Question 3

Question Type: MultipleChoice

NR began to support the base station version of the UBBPg half-width board, which of the following versions started?

Options:

- A- 5G RAN 1.0
- B- 5G RAN 2.0
- C- 5G RAN 2.1
- D- Unsupportable

Answer:

C

Question 4

Question Type: MultipleChoice

To do the 5G transformation of 4G base stations, LTE anchor base stations and NR base stations are required to share the BBU frame, so which of the following practices is feasible?

Options:

- A- Replace BBU3900 with BBU5900
- B- LBBPc is replaced with UBBPg veneer

C- Use UMPTb as the main control board for 4G and NR

D- Use the BBU3910 as the chassis for 4G and NR

Answer:

A, B

Question 5

Question Type: MultipleChoice

In order to verify the successful establishment of NSA services, which of the following items need to be checked?

Options:

A- Whether LTE can ping NR

B- Whether the NR S1-C status is normal

C- Whether the NR S1-U status is normal

D- X2 link status

Answer:

B, C, D

Question 6

Question Type: MultipleChoice

Which of the following MML commands supports unblocking gNodeB cells?

Options:

A- UBL LOCELL

B- UBL CELL

C- UBL GLOCELL

D- UBL NRCELL

Answer:

D

Question 7

Question Type: MultipleChoice

When logging in to the CPE Web Management page, the LTE indicator icon in the upper right is blue and the NR indicator icon is gray, indicating that the NR base station is currently faulty and needs to be dealt with.

Options:

A- Correct

B- Errors

Answer:

B

To Get Premium Files for H35-460 Visit

<https://www.p2pexams.com/products/h35-460>

For More Free Questions Visit

<https://www.p2pexams.com/huawei/pdf/h35-460>

