

Free Questions for DES-DD23 by ebraindumps

Shared by Brennan on 06-06-2022

For More Free Questions and Preparation Resources

Check the Links on Last Page

Question 1

Question Type: MultipleChoice

What rule must be followed during an upgrade procedure with the FS25 expansion shelf?

Options:

- A- FS25 shelf is cabled on a separate private chain
- B- For high performance, the connections from a controller to FS25 shelves must be over FC cables
- C- FS25 shelf must be on the same chain with DS60
- D- If ES40 SAS shelves are on the same chain as an FS25, the maximum number of shelves on that chain is five

Reference: https://www.dell.com/support/kbdoc/en-pk/000082030/71624-memory-requirements-Product Questions:

Version:

and-storage

https://www.dell.com/support/kbdoc/en-pk/000082030/71624-memory-requirements-Product Questions:

Version:

and-storage- configurations

Answer:

Α

Question 2

Question Type: MultipleChoice

What is a requirement to use the PowerProtect DD HA feature?

Options:

- A- Each head unit requires its own FS25 shelf
- B- Head units and nodes require an active/active configuration
- C- A single set of shared storage
- D- Dual set of shared storage configuration

Answer:

D

Question 3

Question Type: MultipleChoice

Nu ti a u a c		
Options:		
- nfs enable		
3- nfs status		
- nfs show clients		
- system show		

С

Question 4

Question Type: MultipleChoice

Which command is used to check if NFS is enabled?

A storage administrator finished the zoning between the PowerProtect DD and the NetWorker backup server. How can they verify that the zoning was completed properly and the server HBA are visible?

Options:	
A- scsitarget initiator show list	
B- scsitarget show initiator list	
C- scsitarget show initiator	
D- scsitarget initiator list	
Answer:	
A	
Λ	
Λ	
Question 5	
Question 5	
Question 5 Question Type: MultipleChoice	ts for a single MTree and is trying to create a new one. An error message is received.
Question 5 Question Type: MultipleChoice	s for a single MTree and is trying to create a new one. An error message is received.
Question 5 Question Type: MultipleChoice An administrator has retained snapshot	s for a single MTree and is trying to create a new one. An error message is received.
Question 5 Question Type: MultipleChoice An administrator has retained snapshot	ts for a single MTree and is trying to create a new one. An error message is received.

- A- The maximum number of snapshots has been exceeded
- B- The user does not have the permission to retain more snapshots
- C- There are not enough snapshot licenses
- D- The DDOS needs to be upgraded

Α


Question 6

Question Type: MultipleChoice

What is the preferred method to ensure backups are protected against deletion or corrupt?

Options:

- A- Encryption
- **B-** Dell EMC Cloud Tier
- **C-** Retention Lock



D

Question 7

Question Type: MultipleChoice

A backup administrator is tasked with monitoring PowerProtect DD capacity metrics. The administrator is backing up 2 TB of data daily with a reduction rate at 5x. After data reduction, subsequent full backups compress down to 100 GB.

The initial backup requires 400 GB with a 10 percent increase in the data each day. Each incremental backup is 200 GB. After data reduction, each incremental backup is 20 GB.

What is the weekly burn rate (GB) after six daily incremental backups and one weekly backup?

Options:

A- 200

B- 220



D- 440

Answer:

Α

Question 8


Question Type: MultipleChoice

An engineer is deploying two PowerProtect DD6900 systems in an HA pair. The installation includes ES40, DS60, and FS25 expansion shelves.

What consideration should be made when cabling the hardware?

Options:

- A- The FS25 shelf must be fully populated
- B- The FS25 shelf should be cabled on a separate chain
- C- The DS60 shelf should be cabled on a separate chain



Answer:	
В	
Question 10	
Question Type: MultipleChoic	<u>e</u>
An administrator monitors inbound traffic is high.	the performance statistics of a PowerProtect DD appliance. Low disk-write rates are shown, and the network
What is the most likely cau	se of this behavior?
Options:	
A- NVRAM failure	
B- Disk failure	
C- Expired segments	
D- Known segments	

Question 11

Question Type: MultipleChoice

An engineer is configuring a PowerProtect DD system for VTL using Fibre Channel. How should the zones be configured?

Options:

- A- Hard zones
- B- Single initiator, multi target
- **C-** Single initiator, single target
- D- Soft zones

Answer:

В

To Get Premium Files for DES-DD23 Visit

https://www.p2pexams.com/products/des-dd23

For More Free Questions Visit

https://www.p2pexams.com/dell-emc/pdf/des-dd23

