# Question 1

**Question Type: MultipleChoice**

Refer to the exhibit.

Rack view  AL_ACP_AL_ACP_RACK

| | |
|---|---|
| 42 | 42 |
| 41 | 41 |
| 40 | 40 |
| 39 | 39 |
| 38 | 38 |
| 37 | 37 |
| 36 | 36 |
| 35 | 35 |
| 34 | 34 |
| 33 | 33 |
| 32 | 32 |
| 31 | 31 |
| 30 | 30 |
| 29 | 29 |
| 28 | 28 |
| 27 | 27 |
| 26 | 26 |
| 25 | 25 |
| 24 | 24 |
| 23 | 23 |
| 22 | 22 |
| 21 | 21 |
| 20 G450 ✅ | 20 |
| 19 | 19 |
| 18 | 18 |
| 17 4850GTS ⚡ | 17 |
| 16 4850GTS ⚡ | 16 |
| 15 | 15 |
| 14 | 14 |
| 13 PIPS Pro1 PDU ⚡ | 13 |
| 12 | 12 |
| 11 PIPS Pro1 PDU | 11 |
| 10 | 10 |
| 09 | 09 |
| 08 DL360 G9 ✅✅ | 08 |
| 07 DL360 G9 ✅✅ | 07 |
| 06 | 06 |
| 05 | 05 |
| 04 | 04 |
| 03 | 03 |
| 02 VNXe3200 ❌ | 02 |
| 01 | 01 |

V1  V2  V3    V4  V5  V6

V1  V2  V3    V4  V5  V6

When a support engineer navigates to Orchestrator's Rack View of an ACP 4200 system, the engineer notices that the V1-V6 slots on the right of the diagram are not populated.

What could be causing this problem?

## Options:

**A-** V1-V6 are used to represent Virtual Machines which are not present in this particular system.

**B-** V1-V6 are used to represent Vertical PDUs which are not present in this particular system.

**C-** V1-V6 are used to represent G450 Media Modules which are not present in this particular system.

**D-** V1-V6 are only used for ACP 100 systems.

## Answer:

A

# Question 2

**Question Type: MultipleChoice**

A support engineer is upgrading a PodFX 3.1 system to ACP 4200 4.0. The engineer is upgrading the ESXi hosts to VMware ESXi 6.5.

Which two statements about this upgrade process are true? (Choose two.)

# Question 3

**Question Type:** **MultipleChoice**

Which command will verify VSP adjacencies?

## Options:

**A-** set isis adjacencies

**B-** show isis adjacencies

**C-** show isis routes

**D-** show ospf routes

## Answer:

B

## Explanation:

https://downloads.avaya.com/css/P8/documents/100180474 (990)

# Question 4

**Question Type:** **MultipleChoice**

Before downloading and applying a PDU patch, you must determine the type of PDU the ACP 4200 is using.

Which two kinds of PDUs are valid? (Choose two.)

## Options:

**A-** Switched

**B-** Synchronized

**C-** Smart

**D-** Stationary

**E-** Static

## Answer:

B, D

# Question 5

**Question Type:** **MultipleChoice**

An ESXi Host server has been replaced due to a fault.

To provide for this replacement, which portion of the Lifecycle Workbook needs to be updated?

## Options:

**A-** Power Cord Wiring

**B-** Serial Numbers

**C-** Network Data

**D-** Switch Wiring

## Answer:

B

# Question 6

**Question Type:** **MultipleChoice**

When deploying the vCenter update, there are certain parameters that must be used.

Which IP address should be used for the Network 1 IP Address?

## Options:

**A-** The Localhost IP address for your datacenter subnet IP interface

**B-** The datacenter facing IP interface IP address and a 32 bit mask

**C-** The Internet facing IP interface IP address and mask

**D-** A temporary IP, from the Management subnet, not already in use

## Answer:

D

# Question 7

**Question Type:** **MultipleChoice**

A customer requires additional Avaya Aura applications to be added to the ACP 4200. This has been reviewed and approved by Avaya's ACP Product Management team. It has been determined that a new computer server is required to meet the expanded resource requirement.

Which three parts of the Lifecycle Workbook need to be updated to provide for the new requirements? (Choose three.)

## Options:

**A-** Contact Info

**B-** ACP 4200 Solution RMU Elevation

**C-** Serial Numbers

**D-** Network Data

**E-** QA Checklist

## Answer:

A, B, C

# Question 8

**Question Type:** **MultipleChoice**

A support engineer is upgrading a PodFX 3.1 system to ACP 4200 4.0. In preparation for upgrading the HPE server firmware, the engineer notices that another colleague has already downloaded files.

Which two files should the engineer use? (Choose two.)

## Options:

**A-** hp-firmware-ilo4-2.60-1.1.i386.rpm

**B-** bp-avaya-dl360g9-g10-ACP-4_0-New-only.iso

**C-** SP99382.exe

**D-** ACP_40_ilo4_261.bin

## Answer:

B, D

## Explanation:

https://support.avaya.com/downloads/download-details.action? contentId=C201811141048316790_5&productId=P1704

# Question 9

**Question Type:** MultipleChoice

Which statement about the LifeCycle Manage Workbook (LCM) and any time there is a change made to the ACP 4200 implementation is true?

## Options:

**A-** The LCM only needs to be updated when hardware devices are changed.

**B-** Retrieve the LCM from ACP 4200 support prior to making any changes.

**C-** The LCM is only needed when receiving the ACP 4200.

**D-** Update the LCM with all changes and submit it via email to podfxsupport@avaya.com.

## Answer:

D

# Question 10

**Question Type:** **MultipleChoice**

Which two upgrade tasks are required before upgrading the ESXi servers to 6.5? (Choose two.)

## Options:

**A-** Upgrade the HP Server iLO firmware.

**B-** Upgrade the PDU firmware.

**C-** Upgrade the switch firmware.

**D-** Upgrade the HP Server firmware.

**Answer:**

A, C

**Explanation:**

https://downloads.avaya.com/css/P8/documents/101061688

# Question 11

Question Type: **MultipleChoice**

A support engineer is tasked with upgrading a CPOD 2.1 system to ACP 4200 4.0.

Which statement about the upgrade process is true?

**A-** Upgrading a CPOD 2.1 system to ACP 4200 4.0 is supported, and a direct upgrade path is supported.

**B-** Upgrading a CPOD 2.1 system to ACP 4200 4.0 is supported only if the Rack enclosure is replaced with a new 48 Inch Deep Model.

**C-** Upgrading a CPOD 2.1 system to ACP 4200 4.0 is not supported.

**D-** Upgrading a CPOD 2.1 system to ACP 4200 4.0 is supported, but a direct upgrade path is only partially supported.

**Answer:**

B

# Question 12

**Question Type:** **MultipleChoice**

Which two statements are considered backup strategy best practices? (Choose two.)

**Options:**

**A-** Create backups of the ACP 4200 system on the storage system inside the pod.

**B-** Do not backup to the ACP 4200 itself, backup to an external location.

**C-** No backups need to be made as the systems in ACP 4200, and the Pod are already reliable.

**D-** VMware snapshots are recommended for virtual appliance backups.

**E-** Determine business continuity, compliance, and regulatory considerations.

## Answer:

B, D