



BICSI INST1-V8 Dumps

Shared by Valenzuela on 15-09-2026

For More Free Questions and Preparation Resources

Check the Links on Last Page



Question 1

Question Type: MultipleChoice

What is the markings for non-conductive optical fiber riser cable?

Options:

- A- OFNP
- B- OFNG
- C- OFNR
- D- OFCR

P2P
exams

Answer:

C

Question 2

Question Type: MultipleChoice

Which is a keyed, contact, moderate loss connector in present use today that is pull & wiggle-proof?

Options:

- A- Opti-Jack
- B- SMA 906
- C- Subscriber Connector (SC)
- D- Straight Tip (ST)

P2P
exams

Answer:

D

Question 3

Question Type: MultipleChoice

Which of the following steps should be performed first when terminating a coaxial cable?

Options:

- A- Verify connector type
- B- Cut the cable
- C- Strip the cable
- D- Fold back the braiding

Answer:

A

Question 4

Question Type: MultipleChoice

Volts are measurement of _____?

Options:

- A- Light reflection
- B- Electrical pressure
- C- Electromagnetic radiation
- D- Sound waves

Answer:

B

Question 5

Question Type: MultipleChoice

Which of the following make the biggest impression on a customer during face-to-face conversation?

Options:

- A- Choice of words
- B- Tone of voice
- C- Body language

Answer:

C

Question 6

Question Type: MultipleChoice

Which of the following items may be used as a substitute device for a pulling eye?

Options:

- A- Wire mesh grip
- B- Fan-out kit
- C- Innerduct
- D- D rings

Answer:

A

Question 7

Question Type: MultipleChoice

What is the recommended minimum amount of aisle space between and around equipment?

Options:

- A- 0.6 m (2')
- B- 1 m (3.3')
- C- 1.2 m (4')
- D- 1.52 m (5')

Answer:

B

Question 8

Question Type: MultipleChoice

You are pre-terminating cable. Where should the labels be placed?

Options:

- A- Near end
- B- Far end
- C- Both ends

P2P
exams

Answer:

C

Question 9

Question Type: MultipleChoice

What is the recommended thickness for plywood that will be mounted on the walls of a telecommunications room?

Options:

- A- 12.7 mm (1/2')
- B- 19 mm (3/4')
- C- 25 mm (1')
- D- 32 mm (1-1/4')

P2P
exams

Answer:

B

Question 10

Question Type: MultipleChoice

Which of the following is permissible if the available firestop assembly is NOT capable of properly restoring the necessary fire rating?

Options:

- A- Substitute products from another assembly
- B- Add more of the product to increase the rating
- C- Obtain written assistance from the manufacturer
- D- Move the installation to another location

Answer:

C

Question 11

Question Type: MultipleChoice

During the troubleshooting phase, what is the first step?

Options:

- A- Verify
- B- Isolate
- C- Repair
- D- Test

Answer:

A

P2P
exams

P2P
exams

To Get Premium Files for INST1-V8 Visit

<https://www.p2pexams.com/products/inst1-v8>

For More Free Questions Visit

<https://www.p2pexams.com/bicsi/pdf/inst1-v8>

20%
DISCOUNT

P2P
exams