Free Questions for H11-879 by dumpshq

Shared by Whitfield on 06-06-2022

For More Free Questions and Preparation Resources

Check the Links on Last Page

Question 1

Which of the following files is necessary to deploy an automatic version upgrade of an eSpace IP phone? () Multiple choice

Options:

A- Version upgrade file B in Bin format.

B- Upgrade policy file

C- Address book

D- Log file

Answer:

A, B

Question 2

There are two terminals, T1 and T2, both registered to the same GK. When T1 calls T2 by number, what is wrong with the following statement? () Multiple choice

Options:

A- The ACF message received by T1 contains the GK call signaling channel transmission address

B- The ACF message received by T1 contains the call signaling channel transmission address of T2

C- After T2 receives the Setup message, it sends an ARQ message to GK

D- After T2 receives the Setup message, it sends an ARQ message to T1

Answer:

A, D

Question 3

Question Type: MultipleChoice

The following are not part of the H.245 capability set ()

Options:

A- H.235

B- H.239

C- H.350

D- H.460

Answer:

C

Question 4

Question Type: **MultipleChoice**

The human eye is more sensitive to brightness than to color. () Correct or Wrong

Options:

A- Correct

B- Wrong

Answer:

A

Question 5

Question Type: MultipleChoice

The SMC2.0 batch number allocation function supports the addition, modification and deletion of unmanageable sites, excluding ISDN sites () Correct or Wrong

Options:

A- Correct

B- Wrong

Answer:

A

Question 6

Question Type: **MultipleChoice**

In the U1900 unified gateway, outgoing calls need to be configured in a certain order. The following configuration process is correct ()
Multiple choice

Options:

A- Office route selection code -> office route -> trunk -> prefix

B- Office route selection code -> Trunk -> Office route -> Prefix

C- Office route selection code -> prefix -> office route -> trunk

D- Office route selection code -> Trunk -> Prefix -> Office route

Answer:

A, C

Question 7

Question Type: **MultipleChoice**

The SMC2.0 resource pool solution can improve the reliability of the videoconferencing system. If the MCU in use suddenly goes down during a conference, which of the following principles will SMC2.0 choose to use as a backup MCU? () Multiple choice

Options:

A- Same service area first

B- MCUs with the same prefix are preferred

C- The MCU with the most remaining resources in the same service area is preferred

D- Among all MCUs, the MCU with the most remaining resources is preferred

Answer:

A, B, C

Question 8

Question Type: MultipleChoice

If IP phone A fails to register with U1900, which of the following situations will not be the cause of the registration failure? ()

A- IP phone A has a network failure

B- The SIP server information in the configuration of IP phone A is incorrectly configured.

C- SIP account and password in IP phone A configuration are wrong

D- The user ID and phone number of IP phone A configured in the U1900 system are inconsistent

Answer:

D

Question 9

Question Type: **MultipleChoice**

When other conditions are the same, the longer the reverberation time of the room, the clearer the sound heard Clarity. () Right or Wrong

Options:

A- Right

B- Wrong

Answer:

B

Question 10

Regarding the IP phones and analog phones in the U1900 system, which of the following statements is correct ()

Options:

A- If you want to successfully register IP phones A and B to the U1900 system, the U1900 system must include the MTU board

B- When IP phones A and B have successfully registered to the same U1900 system, if IP phones A and B are able to dial each other, the U1900 system must include an MTU board

C- When IP phone A and B have successfully registered to the same U1900 system, if IP phone A calls When calling IP phone B, IP phone B is busy, then if you need IP phone A to hear busy Line tone, the U1900 must contain MTU board

D- If IP phone A and analog phone C (directly connected to the ASI board of U1900) are successfully registered to U1900, when A calls C, U1900 may not contain MTU board

Answer:

C

Question 11

Question Type: MultipleChoice

An enterprise has deployed eSight network management, DNS server and DHCP server on its existing network. For deploying 200 IP phones, which of the following methods cannot achieve batch configuration of TR069 parameters? ()

Options:

A- Configure the eSight domain name and IP address mapping in the DNS server

B- Batch delivery via DHCP Option 246 field

C- Use access scan

D- Through the web configuration interface of IP Phone

Answer:

D