Free Questions for H12-311 by actualtestdumps

Shared by Hayden on 06-06-2022

For More Free Questions and Preparation Resources

Check the Links on Last Page

Question 1

Question Type: MultipleChoice

How many management nodes (B) does the eSight Standard Edition support?

Options:

A- 60

B- 2000

C- 5000

D- 20000

Answer:

B

Question 2

Question Type: MultipleChoice

What are the prerequisites for users to implement Layer 3 roaming (Select 3 Answers)?

Options:

A- The two APs of the user roaming switch must have the same SSID.

B- Two APs for user roaming switch must have the same VLAN

C- User roaming requires two AP signals to be covered with overlapping areas

D- The SSID released by the two APs of the user roaming switch must have the same authentication method.

Answer:

A, C, D

Question 3

Question Type: **MultipleChoice**

Which of the following options will cause users to not find a wireless network signal (Select 2 Answers)?

Options:

A- AP is configured with 5G priority, resulting in 2.4G wireless client not searching for signals.

B- The user wireless network card is not enabled or the wireless network card hardware switch is not turned on.

C- The wireless controller is configured with user isolation

D- User wireless network card driver is abnormal

Answer:

B, D

Question 4

Question Type: MultipleChoice

In the direct connection network, the AP and the AC establish a CAPWAP tunnel. The management flow must be encapsulated in the CAPWAP tunnel. The data service flow can be encapsulated in the CAPWAP tunnel.

Options:

A- True

B- False

Answer:

A

Question 5

Question Type: MultipleChoice

To avoid reconfiguration of data when an AP on the network is faulty, you can quickly replace APs by configuring AP replacement.

Options:

A- True

B- False

Answer:

A

Question 6

Question Type: MultipleChoice

To configure a WLAN service, you need to add an AC to the U2000.

Options:

A- True

B- False

Answer:

A

Question 7

Question Type: MultipleChoice

How to deal with the failure of AP and AC version mismatch on a large number of devices.

Options:

A- Upgrade the versions to match each other.

B- Replace the AP device.

C- Replace the switch

D- Check if the POE power supply is normal.

Answer:

A

Question 8

Question Type: **MultipleChoice**

The equipment manufacturer can usually be judged according to the following.

Options:

A- SSID

B- MAC address

C- Encryption type

D- Channel

Answer:

B

Question 9

Question Type: MultipleChoice

The AP or AC performing the connectivity test must be online.

Options:

A- True

B- False

Answer:

A

Question 10

Question Type: MultipleChoice

Which configuration methods does the wireless controller support (Select 3 Answers)?

Options:

A- telnet configuration

B- console port configuration

C- eSight configuration

D- LLDP configuration

Answer:

A, B, C

Question 11

Question Type: MultipleChoice

What are the reasons why APs cannot go online (Select 3 Answers)?

Options:

A- The configuration of the DHCP address pool is incorrect. The AP cannot obtain the address.

B- The AP uses static discovery but the IP address of the AC is incorrect.
The version of

C- AP is inconsistent with the version of AC.

D- The controller adopts no-auth authentication mode.

Answer:

A, B, C

To Get Premium Files for H12-311 Visit

https://www.p2pexams.com/products/h12-311

For More Free Questions Visit

https://www.p2pexams.com/huawei/pdf/h12-311