Free Questions for H35-210 by go4braindumps

Shared by Juarez on 12-12-2023

For More Free Questions and Preparation Resources

Check the Links on Last Page

Question 1

Question Type: MultipleChoice

(multiple) In the GPON network, which of the following reasons may cause the ONU to fail to go online?

Options:

A- The optical power received by the ONU is greater than the overload optical power.

B- The optical power received by the ONU is less than the sensitivity value.

C- There is abnormal attenuation on the ODN line.

D- The ODN line is too long and exceeds the upper line distance set by the system.

Answer:

A, B, C, D

Question 2

Question Type: MultipleChoice

(single) When locating an ADSL fault, what causes the ADSL Modem to fail to activate?

Options:

A- Board failure or port failure

B- Line problem, or MODEM failure

C- Line activation template configuration error

D- The above are possible

Answer:

D

Question 3

Question Type: **MultipleChoice**

(single) Is the following description correct? The level of the MA5600T event can be divided into four levels: critical, major, minor, and warning.

Options:

A- True

B- False

Answer:

A

Question 4

Question Type: MultipleChoice

(single) Is the following description correct? The UA5000 is connected to the lanswitch through the GE. The working mode of the two ports can be auto-negotiation mode and the other mode is mandatory.

Options:

A- True

B- False

Answer:

B

Question 5

Question Type: MultipleChoice

(single) Is the following description correct? The MxU auto-upgrade policy automatically compares the current version of the device with the target version of the policy when the device is powered on. If the device is inconsistent, the device software version is automatically upgraded to the target version.

Options:

A- True

B- False

Answer:

A

Question 6

Question Type: MultipleChoice

(multiple) Which content may be included in the current access network MA5600T patch file?

Options:

A- HP temporary hot patch

B- SPH host hot patch

C- HPYxxx single board software package

D- Main control board main package

Answer:

A, B, C

Question 7

Question Type: MultipleChoice

(single) Is the following description correct? The DC upgrade tool requires the license. If there is no license, the default can be 30 concurrently. If there is a license, the maximum can be 60 concurrent.

Options:

A- True

B- False

Answer:

B

To Get Premium Files for H35-210 Visit

https://www.p2pexams.com/products/h35-210

For More Free Questions Visit

https://www.p2pexams.com/huawei/pdf/h35-210