

Free Questions for 300-625 by dumpshq

Shared by Waller on 18-01-2024

For More Free Questions and Preparation Resources

Check the Links on Last Page

Question 1

Question Type: MultipleChoice

A storage engineer is troubleshooting a Cisco MDS switch upgrade issue. What prevents the completion of a non-d.sruptive upgrade?

Options:

A) The Fibre Channel host initiator is connected.

- B) The Fibre Channel storage target is connected.
- C) The Cisco Fabric Services operation in progress.
- D) The Fibre Channel and FCoE storage targets are connected.

Answer:

А

Question 2

Question Type: MultipleChoice

The principal switch on a Fibre Channel network fails to assign requested domain to a subordinate switch. What are two reasons? (Choose two)

Options:

A) Cisco Fabric Services distribution is not enabled on the switch.

B) The fabric is locked.

C) The requested domain is outside the allowed list.

D) The persistent FC ID feature is not enabled.

E) An existing switch already has the requested domain assigned.

Answer:

A, D

Question 3

Question Type: MultipleChoice

A storage administrator manually configure a storage switch to use a new static domain ID. After issuing an fcdomain restart vsan 1 command, the administrator sees that the switch is still using the existing domain ID. What is the reason why the configuration is not working?

Options:

- A) Static domain IDs apply only after a switch is rebooted.
- B) The disruptive keyword was not used on the command.
- C) Build fabric notifications were not sent to the other switches.
- D) Domain manager fast restart is not enabled on the switch.

Answer:	
A	

Question 4

Question Type: MultipleChoice

A storage network engineer must install and configure a new MDS switch in a data center network. Which two statements about available choices during the MDS switch initial setup are correct? (Choose two,)

Options:

- A) The engineer can choose what will be the administrator account
- **B)** The secure password standard is required.
- C) The engineer can configure the default zone policy.
- D) The engineer can configure the default switch port trunK mode
- E) The engineer does not have the choice to enable or disable full roneset distribution

Answer: B, C

Question 5

Question Type: MultipleChoice

A storage network engineer is implementing disk an ay data replication between two SAN environments in two different data centers not connected via Fibre Channel Which SAN switch feature must be implemented?

Options:

A) FCIP

B) zoning merge over LAN

C) VSAN scoping

D) IVR

Answer:

А

Question 6

Question Type: MultipleChoice

A network engineer must run a core Cisco Nexus 9500 Series Switch as a POAP server for all top-of-rack Cisco Nexus switches Which two network functions must run to provide the POAP service? (Choose two)

Options	
----------------	--

A) DNS

B) F	PXE
-------------	-----

C) BOOTP

D) TFTP


E) DHCP

Answer: C, D

Question 7

Question Type: MultipleChoice

Refer to the exhibit.



Refer to the exhibits A storage network engineer activates a zoneset on MDS-A and verifies the successful activation (Exhibit 1) The engineer is then notified that there is a SAN outage (Exhibit 2) What is the cause of the outage?

Options:

A) Another network engineer activated zoneset ZoneSetMDS-B-VSAN100 on MDS-A.

- B) Another network engineer issued the zone mode enhanced vsan 100 command on another switch in the fabric.
- C) Another network engineer activated the zoneset ZoneSetMDS-B-VSAN100 command on another switch in the fabric.
- D) Another network engineer issued the zone default-zone permit vsan 100 command on another switch in the fabric.

Answer:	
---------	--

А

Question 8

Question Type: MultipleChoice

The principal switch on a Fibre Channel network fails to assign requested domain to a subordinate switch. What are two reasons? (Choose two)

Options:

A) Cisco Fabric Services distribution is not enabled on the switch.

- **B)** The fabric is locked.
- C) The requested domain is outside the allowed list.
- **D)** The persistent FC ID feature is not enabled.
- E) An existing switch already has the requested domain assigned.

Answer:

A, D

To Get Premium Files for 300-625 Visit

https://www.p2pexams.com/products/300-625

For More Free Questions Visit

https://www.p2pexams.com/cisco/pdf/300-625

