

Free Questions for H35-211 by dumpshq

Shared by Mccarty on 07-06-2022

For More Free Questions and Preparation Resources

Check the Links on Last Page

Question 1

Question Type: MultipleChoice

(multiple) What are the possible causes of the UA5000's failure of the power monitoring module to be "Fault"?

Options:

A) The physical connection between the power supply and the system is incorrect.

B) The power supply monitoring module serial communication cable is abnormal.

- C) Adapter board jumper setting error
- D) ESC board failure

Answer: A, B, C

Question 2

Question Type: MultipleChoice

(multiple) What are the possible positioning methods when the "echo" fault occurs in the VoIP PSTN telephony service?

Options:

A) Check if the acoustic echo is caused by the terminal phone.

- **B)** Check if the PSTN port transmit gain is set too large.
- C) Check if the DSP chip input gain (PCM->IP) is set too large.
- D) Check if the EC switch (echo suppression switch) of the peer device is turned on during the call.

Answer:

A, B, C, D

Question 3

Question Type: MultipleChoice

(multiple) What are the possible causes of the UA5000's failure of the power monitoring module to be "Fault"?

Options:

A) The physical connection between the power supply and the system is incorrect.

B) The power supply monitoring module serial communication cable is abnormal.

C) Adapter board jumper setting error

D) ESC board failure

Answer:		
A, B, C		

Question 4

Question Type: MultipleChoice

(multiple) What are the possible positioning methods when the "echo" fault occurs in the VoIP PSTN telephony service?

Options:

A) Check if the acoustic echo is caused by the terminal phone.

- **B)** Check if the PSTN port transmit gain is set too large.
- C) Check if the DSP chip input gain (PCM->IP) is set too large.
- D) Check if the EC switch (echo suppression switch) of the peer device is turned on during the call.

Answer:

A, B, C, D

To Get Premium Files for H35-211 Visit

https://www.p2pexams.com/products/h35-211

For More Free Questions Visit

https://www.p2pexams.com/huawei/pdf/h35-211

