



Free Questions for DES-4421 by certscare

Shared by Estrada on 12-12-2023

For More Free Questions and Preparation Resources

Check the Links on Last Page

Question 1

Question Type: MultipleChoice

The iSM is available under which license(s)?

Options:

- A- OpenManage Enterprise-Modular
- B- iDRAC Express and iDRAC Enterprise
- C- iDRAC Enterprise only
- D- iDRAC Express only

Answer:

B

Question 2

Question Type: MultipleChoice

What type of connection is used by QuickSync 2?

Options:

- A-** Bluetooth
- B-** NFC
- C-** QuickAssist
- D-** LTE

Answer:

A

Question 3

Question Type: MultipleChoice

An administrator has installed the iDRAC Service Module in the OS on a compute sled, they are unable to use its features in the iDRAC web GUI.

What is the likely cause of this issue?

Options:

- A-** OS to iDRAC pass-through feature is not enabled in the iDRAC
- B-** iDRAC Express license is installed
- C-** OS and iDRAC are configured on different networks
- D-** Installed OS is not supported

Answer:

A

Question 4

Question Type: MultipleChoice

What configuration is supported for a fully populated MX740c compute sled?

Options:

- A-** 1 Fabric B mezz card1 Fabric C mezz card with Fabric A being integrated into the system board
- B-** 1 Fabric A mezz card1 Fabric B mezz card with Fabric C being integrated into the system board
- C-** 2 Fabric A mezz cards2 Fabric B mezz cards2 Fabric C mini-mezz cards
- D-** 1 Fabric A mezz card1 Fabric B mezz card1 Fabric C mini-mezz card

Answer:

D

Question 5

Question Type: MultipleChoice

An administrator is configuring a fully populated MX5016s storage sled to be accessed by four MX740c compute sleds. Each compute sled has an H745P Jumbo PERC installed. The disks in the storage sled are evenly distributed across all compute sleds using a Drive-Assigned storage configuration.

What is the maximum number of disks that each compute sled can detect from the MX5016s?

Options:

- A- 1
- B- 2
- C- 4
- D- 16

Answer:

D

Question 6

Question Type: MultipleChoice

A company receives their first MX7000 chassis. They connect all the provided power supply cables into two different PDUs on different power grids for redundancy. Each of the six power supplies is cabled and has green LEDs. One Management Module is present along with all system fans. Grid redundancy is configured as the power redundancy mode. The chassis is fully populated with six compute sleds and one IOM but only two of the six sleds will power on.

What is the possible reason for this issue?

Options:

- A-** An additional IOM is required to power on and manage the remaining sleds.
- B-** Two Management Modules are required to power on the populated chassis.
- C-** Power supply unit redundancy policy was not used.
- D-** Mixed high line and low line AC inputs in the same chassis is not supported.

Answer:

C

Question 7

Question Type: MultipleChoice

Which I/O module(s) supports Full Switch and SmartFabric operating modes?

Options:

- A-** MX9116n and MX5108n
- B-** MX5108 and MX5016s
- C-** MX9116n only

D- MX9116 and MX7116n

Answer:

A

Question 8

Question Type: MultipleChoice

What is a benefit of SmartFabric Services Mode?

Options:

- A-** Topology validation and self-healing
- B-** Load balancing for management layers
- C-** Load balancing for application layers
- D-** Automatic detection of packet collisions

Answer:

B

Question 9

Question Type: MultipleChoice

When running an Open Networking operating system, which IOM functions are provided through OME-M?

Options:

- A- Global and privileged configuration modes
- B- Power control and global configuration mode
- C- Hardware health and power control
- D- Hardware health and global configuration mode

Answer:

D

To Get Premium Files for DES-4421 Visit

<https://www.p2pexams.com/products/des-4421>

For More Free Questions Visit

<https://www.p2pexams.com/dell-emc/pdf/des-4421>

