

Free Questions for H12-425 by braindumpscollection

Shared by Rich on 06-06-2022

For More Free Questions and Preparation Resources

Check the Links on Last Page

Question 1

Question Type: MultipleChoice

If the customer load cannot be power-off, what should be taken care when closing the maintenance bypass switch?

Options:

- A- The maintenance bypass switch can also be closed in the inverter power supply mode
- B- Turn off the inverter, let the UPS be in bypass power supply mode and then close the maintenance bypass switch
- C- First perform EPO then close maintenance switch
- D- Close the maintenance switch first and then execute the EP

Answer:

A, B, D

Question 2

Question Type: MultipleChoice

The reason for using the EPO status interface in the parallel step of the UPS5000-E is ().

Options:

- A- Prevent electric shock and protect personal safety
- B- Power off the load to prevent damage to the load device
- **C-** Protect the battery from discharge
- D- Cut off the output and set the parallel parameters

Answer:

D

Question 3

Question Type: MultipleChoice

In the process of disconnecting the battery pack switch, if there are multiple sets of batteries, first disconnect the main switch between the battery pack and the UPS, and then disconnect the switch of each battery pack

Question 5

Question Type: MultipleChoice

To balance the capacity loss caused by the self-discharge of the battery during the use of the battery, it is necessary to charge the battery continuously and for a long time at constant voltage, which is called ().

Options:

- A- charging
- **B** self-discharge
- **C-** balanced charging
- D- charging test

Answer:

Α

Question 6

Question Type: MultipleChoice

The report functions of NetEco has a variety of presentation forms, including visualization of bar charts, pie charts, graphs, etc.

Options:

A- TRUE

B- FALSE

Answer:

Α

Question 7

Question Type: MultipleChoice

When the temperature detector or smoke detector in the FusionModule1000 generates an alarm, () emits a continuous beeping sound to remind you to take measures as soon as possible to avoid a major accident.

0	n	ti	O	n	S	•
	M	•	$\mathbf{}$		$\mathbf{\mathbf{U}}$	

- A- Electricity or voltage ratio setting error
- B- The corresponding voltage collection line is abnormal.
- C- Corresponding current transformer failure
- D- Intelligent power meter failure

Answer:

A, B, C, D

Question 8

Question Type: MultipleChoice

Huawei NetCol5000-A line-level precision air conditioner mainly solves the hot issue of high-density data center

Options:

A- TRUE

Answer:				
Ą				
uestion 9				
estion Type: MultipleChoice	2			
reating a camera on the N	etEco, users need to obtain the	e IP address of the came	a and ().	
Creating a camera on the N	etEco, users need to obtain the	e IP address of the came	a and ().	
Creating a camera on the N	etEco, users need to obtain the	e IP address of the came	a and ().	
reating a camera on the N	etEco, users need to obtain the	e IP address of the came	a and ().	
	etEco, users need to obtain the	e IP address of the came	a and ().	
Options:	etEco, users need to obtain the	e IP address of the came	a and ().	
Options: - Camera pixel	etEco, users need to obtain the	e IP address of the came	a and ().	
Options: A- Camera pixel B- Camera code		e IP address of the came	a and ().	
Options: A- Camera pixel B- Camera code C- Camera installation posit		e IP address of the came	a and ().	
Options: A- Camera pixel B- Camera code C- Camera installation posit D- Camera luminance		e IP address of the came	a and ().	

		_	_ 4		_		- 4	
IJ	ш	e	St	Ш	O	n	-1	()
	\mathbf{v}	~	\mathbf{v}	ч.	•			_

Question Type: MultipleChoice

On the NetEco, users can create domain, such as parks, building and rooms.

Options:

A- TRUE

B- FALSE

Answer:

Α

Question 11

Question Type: MultipleChoice

After all the NetEco monitoring cables are connected, users need to check ().

Options:

- A- Power cables and signal cables are bound separately.
- **B-** Proper redundancy is reserved at connectors of signal cables.
- **C-** Signal cable connectors are intact.
- **D-** Proper redundancy is reserved at the turning point for signal cables.

Answer:

A, B, C, D

Question 12

Question Type: MultipleChoice

On the NetEco, users can viewed detailed camera information such as the camera name, code, IP address.

	4.5		
	nti	\mathbf{or}	16.
V	PLI		IS:

A- TRUE

B- FALSE

Answer:

Α

To Get Premium Files for H12-425 Visit

https://www.p2pexams.com/products/h12-425

For More Free Questions Visit

https://www.p2pexams.com/huawei/pdf/h12-425

